



ABANDONED MINE LAND INSPECTION

PROJECT NAME	PROJECT NO.	GRANT YEAR	REPORT NUMBER
Golden Pond Gob Removal	18302	2018	HNM0008620

CONTRACT INFORMATION		
CONTRACT NUMBER	EXPIRATION DATE	PERCENT OF CONTRACT COMPLETED
C196013	03/31/21	2
CONTRACTOR NAME		ENGINEER NAME
Russell County Reclamation, LLC		SCOTTY COX
SITE CONTACT PERSON: Kevin Large		

INSPECTION DATE	ARRIVAL	DEPARTURE	GROUND CONDITION
04/02/19	03:00 PM	04:45 PM	WET
04/17/19	09:15 AM	11:00 AM	WET
04/24/19	03:00 PM	04:30 PM	WET

INSPECTION BY	ATTACHMENTS
MCDONALD-TAYLOR, H.	

COMMENTS

Excavation of material continues, with the company still excavating in layers of 18 inches. The discharge from the structure was estimated to be approximately 1 gallon per minute and was clear. The company is working to drain the northern portion of the pond to give better access to the area approved for building construction. A photo of the site is shown below.

ABANDONED MINE LAND INSPECTION

