

## COMMONWEALTH OF VIRGINIA DEPARTMENT OF MINES, MINERALS AND ENERGY DIVISION OF MINED LAND RECLAMATION P.O. DRAWER 900, BIG STONE GAP, VA 24219 TELEPHONE: (276) 523-8198

## ABANDONED MINE LAND INSPECTION

PROJECT NAME		PROJECT NO.	GRANT YEAR	REPORT NUMBER			
Golden Pond Gob Removal		18302	2018	HNM0008781			
CONTRACT INFORMATION							
CONTRACT NUMBER	EXPIRATION DATE		PERCENT OF CONTRACT COMPLETED				
C196013	03/31/21		8				
CONTRACTOR NAME			ENGINEER NAME				
Russell County Reclamation, LLC			SCOTTY COX				
SITE CONTACT PERSON: Kevin Large							

INSPECTION DATE	ARRIVAL	DEPARTURE	GROUND CONDITION
08/06/19	03:30 PM	05:00 PM	DRY
08/15/19	02:00 PM	02:45 PM	DRY

INSPECTION BY	ATTACHMENTS
MCDONALD-TAYLOR, H.	

## COMMENTS

Material removal continued throughout the month. The company continued to excavate from the building zone during August. Below are two photos documenting that the material was excavated to solid ground in this area. A photo of the site is shown below.





COMMONWEALTH OF VIRGINIA DEPARTMENT OF MINES, MINERALS AND ENERGY DIVISION OF MINED LAND RECLAMATION P.O. DRAWER 900, BIG STONE GAP, VA 24219 TELEPHONE: (276) 523-8198

ABANDONED MINE LAND INSPECTION