



COMMONWEALTH OF VIRGINIA
 DEPARTMENT OF MINES, MINERALS AND ENERGY
 DIVISION OF MINED LAND RECLAMATION
 P.O. DRAWER 900, BIG STONE GAP, VA 24219
 TELEPHONE: (276) 523-8198

HNM0008826

ABANDONED MINE LAND INSPECTION

PROJECT NAME	PROJECT NO.	GRANT YEAR	REPORT NUMBER
Golden Pond Gob Removal	18302	2018	HNM0008826

CONTRACT INFORMATION		
CONTRACT NUMBER	EXPIRATION DATE	PERCENT OF CONTRACT COMPLETED
C196013	03/31/21	15
CONTRACTOR NAME		ENGINEER NAME
Russell County Reclamation, LLC		SCOTTY COX
SITE CONTACT PERSON: Kevin Large		

INSPECTION DATE	ARRIVAL	DEPARTURE	GROUND CONDITION
09/11/19	02:00 PM	03:30 PM	WET
09/16/19	09:15 AM	10:15 PM	WET
09/26/19	03:00 PM	03:30 PM	WET

INSPECTION BY	ATTACHMENTS
MCDONALD-TAYLOR, H.	

COMMENTS

Material removal continued throughout the month. The company continued to excavate from the building zone during September. Sumps between the structure and permitted sediment ponds were cleaned on September 19th. Photos of the site are shown below.

ABANDONED MINE LAND INSPECTION





COMMONWEALTH OF VIRGINIA
DEPARTMENT OF MINES, MINERALS AND ENERGY
DIVISION OF MINED LAND RECLAMATION
P.O. DRAWER 900, BIG STONE GAP, VA 24219
TELEPHONE: (276) 523-8198

HNM0008826

ABANDONED MINE LAND INSPECTION