



ABANDONED MINE LAND INSPECTION

PROJECT NAME	PROJECT NO.	GRANT YEAR	REPORT NUMBER
Golden Pond Gob Removal	18302	2018	HNM0009752

CONTRACT INFORMATION		
CONTRACT NUMBER	EXPIRATION DATE	PERCENT OF CONTRACT COMPLETED
C196013	03/31/21	95
CONTRACTOR NAME		ENGINEER NAME
Russell County Reclamation, LLC		SCOTTY COX
SITE CONTACT PERSON: Kevin Large		

INSPECTION DATE	ARRIVAL	DEPARTURE	GROUND CONDITION
08/16/21	04:00 PM	04:30 PM	DRY
08/24/21	04:00 PM	04:45 PM	DRY

INSPECTION BY	ATTACHMENTS
MCDONALD-TAYLOR, H.	

COMMENTS

Material removal is now complete and the entire area has been covered with a mix of shot rock and soil. The site will be seeded under the 2021 Revegetation Project. Photos of the site are shown below.



ABANDONED MINE LAND INSPECTION

