



COMMONWEALTH OF VIRGINIA
DEPARTMENT OF MINES, MINERALS AND ENERGY
DIVISION OF MINED LAND RECLAMATION
P.O. DRAWER 900, BIG STONE GAP, VA 24219
TELEPHONE: (276) 523-8198

HNM0009564

ABANDONED MINE LAND INSPECTION

| PROJECT NAME | PROJECT NO. | GRANT YEAR | REPORT NUMBER |
|--------------------------|-------------|------------|---------------|
| Project Reclaim Phase II | 91806 | 2018 | HNM0009564 |

| CONTRACT INFORMATION | | |
|----------------------------------|-----------------|-------------------------------|
| CONTRACT NUMBER | EXPIRATION DATE | PERCENT OF CONTRACT COMPLETED |
| | | 20 |
| CONTRACTOR NAME | | ENGINEER NAME |
| | | |
| SITE CONTACT PERSON: Kevin Large | | |

| INSPECTION DATE | ARRIVAL | DEPARTURE | GROUND CONDITION |
|-----------------|----------|-----------|------------------|
| 03/04/21 | 03:30 PM | 04:30 PM | WET |
| 03/08/21 | 03:30 PM | 04:30 PM | WET |
| 03/22/21 | 04:00 PM | 04:30 PM | WET |

| INSPECTION BY | ATTACHMENTS |
|---------------------|-------------|
| MCDONALD-TAYLOR, H. | |

COMMENTS

The contract for Project Reclaim Phase II was signed on 12/28/21 and a Notice to Proceed was issued the same day. Work at the site was already on going from Project Reclaim Phase I. Material haulage transitioned from Phase I to Phase II on the day the contract was signed. Material haulage continues daily on the project.

Invoice #2 requested payment in the amount of \$169,023.92. Payment of the invoice was recommended. Photos of the site are shown below.



ABANDONED MINE LAND INSPECTION

