



ABANDONED MINE LAND INSPECTION

PROJECT NAME	PROJECT NO.	GRANT YEAR	REPORT NUMBER
Project Reclaim Phase II	91806	2018	HNM0009664

CONTRACT INFORMATION		
CONTRACT NUMBER	EXPIRATION DATE	PERCENT OF CONTRACT COMPLETED
		80
CONTRACTOR NAME		ENGINEER NAME
SITE CONTACT PERSON: Kevin Large		

INSPECTION DATE	ARRIVAL	DEPARTURE	GROUND CONDITION
06/08/21	04:00 PM	04:30 PM	WET
06/22/21	04:00 PM	04:30 PM	WET

INSPECTION BY	ATTACHMENTS
MCDONALD-TAYLOR, H.	

COMMENTS

The contract for Project Reclaim Phase II was signed on 12/28/21 and a Notice to Proceed was issued the same day. Work at the site was already on going from Project Reclaim Phase I. Material haulage transitioned from Phase I to Phase II on the day the contract was signed. Material haulage continues daily on the project. Removal of fines is nearly complete as well as construction of the retaining pond at the lower end of the site. Berms around the structure have been covered with a layer of topsoil.

Application for Payment #5 requested payment in the amount of \$199,344.48. Payment of the invoice was recommended. Photos of the site are shown below.



ABANDONED MINE LAND INSPECTION

