



ABANDONED MINE LAND INSPECTION

PROJECT NAME	PROJECT NO.	GRANT YEAR	REPORT NUMBER
Project Reclaim Phase II	91806	2018	HNM0009861

CONTRACT INFORMATION		
CONTRACT NUMBER	EXPIRATION DATE	PERCENT OF CONTRACT COMPLETED
		100
CONTRACTOR NAME		ENGINEER NAME
SITE CONTACT PERSON: Kevin Large		

INSPECTION DATE	ARRIVAL	DEPARTURE	GROUND CONDITION
10/18/21	08:30 AM	10:00 AM	DRY
10/29/21	03:30 PM	04:30 PM	WET

INSPECTION BY	ATTACHMENTS
MCDONALD-TAYLOR, H.	

COMMENTS

The contract for Project Reclaim Phase II was signed on 12/28/21 and a Notice to Proceed was issued the same day. Work at the site was already on going from Project Reclaim Phase I. Material haulage transitioned from Phase I to Phase II on the day the contract was signed. Work at the site is complete. Seeding of the structure will occur under the 2021 Revegetation Project. Seeding of the site began on 10/19/21 and concluded on 10/29/21. With completion of the seeding project Project Reclaim Phase II is now eligible for release. Photos of the seeded site are shown below.



ABANDONED MINE LAND INSPECTION

